

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer /Assistant Executive Engineer)

- | | | | |
|---|---|---|---|
| 1 | Name of School | : | Progressive English School Wadihuda, Payangadi |
| 2 | Name of officer | : | Aswini Chemmenchery |
| 3 | Location | : | Madayippara |
| 4 | Period for which the certificate issued | : | 01-06-2023 to 31-05-2024 |
| 5 | Type of building | : | Permenant Three Storied Building R.C.C
1) 71.36 m x 6.63m x 3.65m - 3 Storied
2) 48 m x 6.6m x 3.65m - 3 Storied
3) 38.8 m x 6.00m x 3.5m - 3 Storied

Class Room (33Nos.), Seminar Hall (1No.), Staff Room (2Nos.), Office Room (2No.), Principal Room (1No.), Council Room (1No.), Stock Room (1No.), Toilet (80Nos.), Work Area (1No.), PT Room (1No.), Library (1No.), Biology Lab (1No.), Maths Lab (1No.), Activity Room (1No.), Physics Lab (1No.), Chemistry Lab (1No.), Computer Lab (1No.) |
| 6 | Nature of defects, if any | : | |
| | a) Foundation and basement | : | |
| | b) Super structure | : | |
| | c) Door and Windows | : | |
| | d) Wood work wrought and put up | : | NIL |
| | e) Roof | : | |
| | f) Flooring | : | |
| | g) Miscellaneous | : | |
| 7 | Any major defects noticed which will render the building unsafe in any manner | : | No |
| 8 | Whether maintenance works have been done properly | : | Yes |
| 9 | Whether the structure is sound or not for conducting classes | : | Yes, the structure is safe for conducting classes under normal weather and wind conditions |


Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 24.05.2023 and found to be fit to conduct classes, for the period for the reasons stated above.



Place: Madayi
Date: 24.05.2023

Signature: 
Designation:

ASSISTANT ENGINEER
LID & EW SECTION
MADAYI GRAMA PANCHAYATH



Sujithra. R
Principal
Progressive English School
(Senior Secondary)
WADIHUDA, PAYANGADI-670303



For PROGRESSIVE ENGLISH SCHOOL


Manager

TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer /Assistant Executive Engineer)

- 1 Name of School : Prograssive English School Wadihuda,Payangadi
- 2 Name of officer : Aswini Chemmenchery
- 3 Location : Madayippara
- 4 Period for which the certificate issued : 01-06-2023 to 31-05-2024
- 5 Type of building : Permenant Three Storied Building R.C.C
- 1) 25.00 m x 8.40m x 3.6m - 3 Storied
- 2) 50.20 m x 8.40m x 3.6m - 3 Storied
- 3) 34.30 m x 8.40m x 3.6m - 3 Storied
- Class Room (29Nos.), Office Room (1No.), Play Room (1No.), Aunt's Room (1No.), Staff Room (4Nos.), Special Education Room (1No.), Store Room (1No.), Lab (3Nos.), Library (1No.), IT Lab (1No.), Sports Room (1No.)
- 6 Nature of defects, If any :
- a) Foundation and basement :
- b) Super structure :
- c) Door and Windows : NIL
- d) Wood work wrought and put up :
- e) Roof :
- f) Flooring :
- g) Miscelieneous :
- 7 Any major defects noticed which will render thebuilding unsafe in any manner : No
- 8 Whether maintenance works have been done properly : Yes
- 9 Whether the structure is sound or not for conducting classes : Yes, the structure is safe for conducting classes under normal weather and wind conditions

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.

2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 24.05.2023 and found to be fit to conduct classes, for the period for the reasons stated above.

Place: Madayippara

Date: 24.05.2023

Signature:

Designation:

ASSISTANT ENGINEER
LID & EW SECTION
MADAYI GRAMAMPANCHAYATH



Sujithra. R
Principat
Progressive English School
(Senior Secondary)
WADIHUDA, PAYANGADI-670303



For PROGRESSIVE ENGLISH SCHOOL


Manager